


T-1000



UV 3D Printer **Manual** v1.8

The manual covers the most basic operations. For more information, please check g3dsys.com.

CONTENTS

Introduction	1
Specifications	1
Package Contents	3
About 3D Printing	4
Introduction	4
T-1000 UV 3D printing	4
Digital Light Processing	5
Photopolymer resin	5
Self-leveling vat	6
Getting to know the T-1000	7
T-1000 Diagram	7
Safety	9
Explanation of the symbols	10
Terms and conditions	11
Getting started	12
Setting the build plate	12
Setting the vat	13
Removing the vat	14
Powering on	15
Powering down	16
Connecting your device to T-1000 Printer WiFi	17
Connecting via Ethernet	18
Changing details of T-1000 Printer WiFi settings	20
Connecting T-1000 to Home WiFi	21
Resetting WiFi connection	23
G3D Web User Interface	24
Updating the G3D Web User Interface	25
Printing with T-1000	26
Uploading a new file	26
Choosing a file	26
Uploading files from USB	27
Deleting a file	27
Setting cure time	28
Calibrating the vat	30
Positioning the build plate	33
Filling the vat	35
Printing	35
Pause printing	36
Abort printing	36
Adjusting the projector	37
Adjusting the xy resolution of projector	37
Focusing the projector	41

CONTENTS

Cleaning guide	47
Raising the build plate	47
Removing the build plate	47
G3D print workstation kit	49
Removing the print	50
Cleaning the print	50
Cleaning the vat	52
Cleaning the projector	53
Cleaning the T-1000	53
Vat handling	54
Troubleshooting	55
Contact	56
Resin Cure Matrix	57

SPECIFICATIONS

HARDWARE

Printer Technology	DLP/SLA
Build Volume (Max)	441 cu. in 7,225,344 cu. mm
Build Dimension (Max)	7.06 in(L) x 5.29 in(W) x 11.81 in(H) 179.20 mm(L) x 134.40 mm(W) x 300.00 mm(H)
Thickness per layer(Z axis)	Max 0.00472 in 120 µm Min 0.00029 in 7.50 µm
Print Speed	25 min/in - 35min/in 0.98 min/mm - 1.38 min/mm
Material	Photopolymer
Printer Weight	29 kg 63.9341 lbs
Dimension	H 26.71 in 678.50 mm W 17.86 in 453.60 mm L 11.66 in 296.13 mm
Input	110 - 220 VAC, 0.8A 50 Hz - 60 Hz
Operating Temperature	17°C - 40°C 62.6°F - 104°F

SOFTWARE

Connectivity	WiFi / USB / Ethernet
System compatibility	Windows / Mac / Linux
Supported file	G3D, G3L / importable STL



SPECIFICATIONS

XY RESOLUTION TO BUILD VOLUME


Resolution	Build Dimension	Build Volume	Speed
100 μm	4.03 in x 3.02 in x 11.81 in 102.4 mm x 76.8 mm x 300 mm	143.97 cu. In 2359296 cu. mm	25 min/in 0.98 min/mm
125 μm	5.04 in x 3.78 x 11.81 in 128 mm x 96 mm x 300 mm	224.96 cu. In 3686400 cu. mm	32 min/in 1.26 min/mm
150 μm	6.05 in x 4.54 in x 11.81 in 153.6 mm x 115.2 mm x 300 mm	323.94 cu. In 5308416 cu. mm	35 min/in 1.38 min/mm
175 μm	7.06 in x 5.29 in x 11.81 in 179.2 mm x 134.4 mm x 300 mm	440.92 cu. In 7225344 cu. mm	35 min/in 1.38 min/mm

PACKAGE CONTENTS

Be sure all items listed here were included with your printer.



Resin




Build Plate



Clippers



Scraper



Vat

ABOUT 3D PRINTING

INTRODUCTION

3D printing refers to creation of three-dimensional objects from a cad file, one layer at a time. 3D printing is used in rapid prototyping and additive manufacturing.


The most common and widely used in additive 3D printing are fused deposition modeling (FDM), stereolithography (SLA) and digital light processing (DLP).

One of the main advantages of 3D printing is the speed at which parts can be produced compared to traditional manufacturing methods. Another advantage in 3D printing is low cost in labor where it requires an operator to press a button, 3D printer then follows an automated process to produce the part. 3D printing allows customization and has a relatively small learning curve to operate successfully.


T-1000 UV 3D PRINTING

The T-1000 is a digital light processing (DLP) 3D printer which uses ultraviolet light to cure the resin. Prints are produced by “photopolymerization” or hardening series of thin layers.

T-1000 UV 3D printing begins with a 3D model from a computer-aided design (CAD) software, you need to export the 3D model file as an STL file. Once you have the STL file, preparation must be done in the G3D Layout and Slice software. Import the STL file into the Layout module of the software, this is where you modify, orient and add support or base. After the layout is complete, save the file as a G3L file. In the Slice module of the software, open the G3L file, this is where you will slice the model of the file, in order to divide it into horizontal layers or known as the Z layer thickness or height. Once the model of the file is sliced, save the file as G3D file, this is now ready to upload in the G3D Web UI that will integrate with the T-1000 for printing.



ABOUT 3D PRINTING




DIGITAL LIGHT PROCESSING

T-1000 has a completely custom designed UV LED light engine that uses the DLP technology to cure liquid resin into solid prints. Digital Light Processing (DLP) is a display device that uses a digital micromirror device. The display device is a projector that will flash a single image of each layer across the entire build plate at once. Image is displayed as square pixels therefore the print is composed of voxels.

PHOTOPOLYMER RESIN

G3D Photopolymer Resin is a type of polymer that changes its physical properties when exposed to UV light. Photopolymer liquid plastic resin turns to solid when introduced to a specific light source.

G3D Resins have optimal settings that can be your reference as your base line when your printer is set to XY:175 microns and Z Layer: 120 microns. Consult to the Resin Cure Matrix for more info about cure time settings.



ABOUT 3D PRINTING

SELF-LEVELING VAT


The T-1000 has a self-leveling vat system which ensures accurate prints. After several prints there's a possibility that the build plate can misalign after several usage. An unlevel build plate can cause first layer issues that can result in poor adhesion.

It is best to position the build plate before you print. This process will enable the printer to self-level the vat and align the build plate.

Ensure to untighten all vat lock screws before you press <□ Position Build Plate> button or this can damage the self-leveling system of the printer.


If the printer is newly purchased or you will use a new vat on the printer, untighten all vat lock screws and release all calibration levers before you press <□ Position Build Plate> button.

SELF-LEVELING VAT SYSTEM




After self-leveling, lock all calibration levers and tighten all vat lock screws to prepare for printing.

GETTING TO KNOW THE T-1000



- | | |
|---------------------------------|------------------------|
| 1 Build plate lock screw | 7 Servo panel |
| 2 Build plate | 8 USB port |
| 3 Acme thread | 9 Ethernet port |
| 4 Vat | 10 WiFi reset |
| 5 Vat lock screw | 11 Power button |
| 6 Calibration lever | |

GETTING TO KNOW THE T-1000



- 12** Lifting handle
- 13** Main switch
- 14** Fuse holder
- 15** Power cable

SAFETY

Please read the following safety precautions before operating the T-1000 UV 3D printer.



ELECTRICAL

- Do not modify or disassemble the printer.
- Modification to the printer voids warranty.
- Ensure to discharge static electricity when you configure the printer or projector.
- Do not open front panel, rear panel and electronic panel while power is on.

OPERATION

- Keep printer in a well-ventilated area.
- Do not stare at the uv light for a long period of time during operation. It can cause permanent loss of vision.
- Do not operate with wet hands.
- Shake the resin bottle well before each use.
- Uninterruptible power supply recommended.

GUIDELINES

- Do not expose printer to extremely high temperatures, such as direct sunlight, flame or other sources of heat.
- Maintain the printer in a flat and sturdy surface.
- Keep printer dry.
- Do not remove the FEP sticker/film on the vat. It is for the vat's protection, manufacturer's warranty will be void if it's damaged or removed.

EXPLANATION OF THE SYMBOLS

Symbol	Description
	AC voltage
	Indoor use only
	<p>RECYCLING</p> <p>This product bears the selective sorting symbol for Waste electrical and electronic equipment (WEEE). This means that this product must be handled pursuant to European directive 2012/19/EU in order to be recycled or dismantled to minimize its impact on the environment.</p> <p>User has the choice to give his product to a competent recycling organization or to the retailer when he buys a new electrical or electronic equipment.</p>
	Proof of compliance with the Canadian national standards adopted by the Standards Council of Canada (SCC) and US national standards.

TERMS AND CONDITIONS

Please be advised of the following terms regarding this manual: All information in this manual is subject to change at any time without notice and is provided for convenience purposes only. G3D reserves the right to modify or revise this manual in its sole discretion and at any time. You agree to be bound by any modifications and/or revisions. Contact the G3D Support Team for up-to-date information. The design of this manual and all text, graphics, information, content, and other material are protected by copyright and other laws. All rights reserved. Certain trademarks, trade names, service marks, and logos used in this manual are registered and unregistered trademarks, trade names and service marks of G3D and its affiliates. Nothing contained in this manual grants or should be construed as granting, by implication, estoppel, or otherwise, any license or right to use any marks without the written permission of G3D. Any unauthorized use of any information, materials, or marks may violate copyright laws, trademark laws, laws of privacy and publicity, and/or other laws and regulations.

DISCLAIMER. Neither G3D nor any of our affiliates warrants the accuracy or completeness of the information, products, or services provided by or through this manual, which are provided "as is" and without any express or implied warranties of any kind, including warranties of merchantability, fitness for a particular purpose, or non-infringement of intellectual property. To the fullest extent permissible by the applicable law, we hereby disclaim all liability for product defect of failure of for the claims that are due to normal wear, product misuse or abuse, product modification, improper product selection, non-compliance with any codes, or misappropriation. To the fullest extent permissible by the applicable law, we hereby disclaim any and all responsibility, risk, liability, and damages arising out of death or personal injury resulting from assembly or operation of our products. G3D assumes no responsibility, nor will be liable, for any damages to, or any viruses or malware that may infect your computer, telecommunication equipment, or other property caused by arising from your downloading of any information or materials related to G3D products. The foregoing excluding do not apply to the extent prohibited by law: please refer to your local laws for any such prohibitions.


LIMITATIONS OF LIABILITY. In no event will G3D or any of our respective officers, directors, employees, shareholders, affiliates, agents, successors, or assigns, nor any party involved in the creation or production of our products, be liable to you or anyone else for any indirect, special, punitive, incidental, or consequential damages (including, without limitation, those resulting from lost profits, lost data, or business interruption) arising out of the use, inability to use, or the results of use of this manual, whether based on warranty, contract, tort, or any other legal theory and whether or not advised of the possibility of such damages. The foregoing limitations of liability do not apply to the extent prohibited by law: please refer to your local laws for any such prohibitions.

CHOICE OF LAW; JURISDICTION. These terms will be governed by and construed in accordance with the laws of the Philippines, without giving effect to any principles of conflicts of laws. Any action seeking legal or equitable relief arising out of or relating to these terms or this manual will be brought only in the courts of the Republic of the Philippines.


GETTING STARTED

SETTING THE BUILD PLATE


1. Remove the build plate lock screw.



2. Insert the build plate.



3. Insert and lock the build plate lock screw.




GETTING STARTED

SETTING THE VAT


 See “Vat handling” on page 54.

1. Untighten all vat lock screws.




2. Insert the vat.

*Spout should be at the back right of the printer.




3. Tighten all vat lock screws.




GETTING STARTED

REMOVING THE VAT

1. Untighten all vat lock screws.




2. Remove the vat.




GETTING STARTED

POWERING ON


1. Plug the power cable into a power outlet. Uninterruptible power supply recommended.



2. Turn on main switch.




3. Press <⏻> power button for 2-3 seconds. A red light-emitting diode (LED) will illuminate from the power button.




GETTING STARTED

POWERING DOWN


1. Press <⏻> power button and hold it down for 5 seconds then release the power button. Wait until the light goes off.



2. Turn off main switch.




3. Unplug the power cable.



GETTING STARTED

CONNECTING YOUR DEVICE TO T-1000 PRINTER WIFI



1. Search the “G3DPrinter” default (SSID) Printer WiFi in the network. It automatically appears 15 seconds after you power on the T-1000.



2. Enter the password “G3D54321” to connect.

password

3. In your web browser, type the default hostname <g3dprint:8080> in the url box and press enter.




GETTING STARTED

After an initial login, you will now see your ip address in the information box.



CONNECTING VIA ETHERNET

 Once you join your Home WiFi you can use Ethernet or use Ethernet only.



GETTING STARTED


CONNECTING VIA ETHERNET

This is for desktop without wireless capability to connect to the T-1000.

Equipment:

- Wired Router
- Power adapter with power cord

1. Plug the power adapter into a socket.
2. Connect one end of an ethernet cable into your desktop's network adapter.
3. Connect the other end of that ethernet cable on the port of your router.
4. Plug one end of an ethernet cable to ethernet port of T-1000.
5. Plug one end of that ethernet cable to the router.
6. Type g3dprint:8080 in the web browser, then press enter.



GETTING STARTED


CHANGING DETAILS OF T-1000 PRINTER WIFI SETTINGS

This is optional unless you have multiple printers.


1. Press <⚙>cogwheel icon.




2. Select <Printer WiFi>.



3. A printer configuration window will appear after you select the Printer WiFi. You need to type your new SSID, new password and new hostname. Only alphanumeric characters, underscore or dash are allowed for SSID and Hostname. Password should be ≥ 8 alphanumeric characters.




4. Save settings and confirm.



GETTING STARTED

5. Printer will shutdown after you press the save button.
6. Push <⏻>power button to turn on the printer.



OPTIONAL IF YOU CHANGE YOUR PRINTER WIFI

1. Search and connect to your <NewSSID> from your WiFi network.
2. Enter your <NewPassword> to connect.
3. Open the web browser and type your <NewHostname:8080> to access the G3D Web UI.




CONNECTING T-1000 TO HOME WIFI

This is optional, you do not necessarily need to connect the printer to your Home WiFi unless you want to receive updates.

1. Press <⚙️> cogwheel icon.



2. Select <Home WiFi>.




GETTING STARTED

3. A printer configuration window will appear and you need to type your home SSID and home password.



4. Join settings and confirm.




5. Printer will shutdown after you press the join button.
6. Push <⏻>power button to turn on the printer.
7. Connect the device to Home WiFi where the printer is also connected.
8. Wait 30 seconds and hit <🔄> refresh button.
9. In web browser, if you haven't changed the hostname configuration, type <g3dprint:8080> in the url box and press enter to access the G3D Web UI.

GETTING STARTED

RESETTING WIFI CONNECTION

Once you are connected to your Home WiFi. The only way to re-connect your device to T-1000 Printer WiFi is to push manually the printer's reset WiFi switch, located at the left panel of printer. Use a small pin to push the WiFi reset. This resets all of your WiFi settings to default.



1. Push down the WiFi reset until the printer shuts down.
2. Push <Ⓞ>power button to turn on printer.
3. Search and connect to "G3DPrinter" SSID using the default settings.


SSID : G3DPrinter
Password : G3D54321

4. In web browser, type the default hostname <g3dprint:8080> in the url box and press enter to access the Web UI.

GETTING STARTED

G3D WEB USER INTERFACE

The T-1000 has an onboard web interface which is the Web UI. It integrates with the T-1000 to print 3D objects.




GETTING STARTED

UPDATING THE G3D WEB UI

When we update the G3D Web UI, you will receive a notification.

1. Make sure printer is connected to the internet.
2. Press <🔔> update alert button.
3. Press <Yes> button to confirm.
4. Printer will shutdown after an update.
5. Push <🔌> power button to turn on printer.

☰ For ease of use, add a bookmark to your web user interface.




PRINTING WITH T-1000

UPLOADING A NEW FILE

Layout and slicing must be done before to prepare the G3D file, please check Layout and Slice manual for more details.


1. Press <New File> button.
2. Select a file. The selected .g3d file will be uploaded in G3D Web UI.



CHOOSING A FILE

The G3D Web UI has several 3D files ready for printing. Layout and Slice software allows you to create .g3d files. Layout and Slice software allows the importation of 3D files in preparation for printing.

1. Press <Choose File> button.
2. Select a file.




PRINTING WITH T-1000

UPLOADING FILES FROM USB

You can print a file from your USB by plugging it in the printer's USB port. All .g3d files in the root of the USB will be automatically detected by the software and will be in the dropdown list of the G3D Web UI.


DELETING A FILE

Select a file and press <Delete File> button.




PRINTING WITH T-1000

3. Press <  Pre-print File > button.



SETTING CURE TIME

1. Input the curing details.



- 
- 

PRINTING WITH T-1000

- ☰ Check the XY resolution of the file in the info box. Always confirm that your printer is set to the correct XY.


Information

Filename
Sphere.g3d

XY Resolution (μm)
175

Z Layer Thickness (μm)
120

Estimated Time (hh:mm)

01:39:00

Total Layers to Print
589

Total Print Volume (ml)
38

XY Resolution (μm)
175

XY RESOLUTION OF FILE: 175 μm


PRINTING WITH T-1000

CALIBRATING THE VAT


It is important to level the vat after you purchase your printer or when you need to replace a vat.

- ☰ See “Removing the vat” on page 14 to replace a vat.
- ☰ See “Setting the vat” on page 13 to replace a vat.

1. Untighten all vat lock screws.




2. Release all calibration levers.



PRINTING WITH T-1000

CALIBRATING THE VAT

3. Gently push down the sides of the vat to check if the calibration levers are in unlocked position.



4. Press Position Build Plate> button and <Yes> button to confirm.
5. Wait until movement has stopped.




FIG. 1




FIG. 2




FIG. 3






FIG. 4


6. Lock all calibration levers.



LEFT



CENTER




RIGHT

PRINTING WITH T-1000

CALIBRATING THE VAT

7. Tighten all vat lock screws.




PRINTING WITH T-1000


POSITIONING THE BUILD PLATE

 You must always position the build plate before printing.

1. Untighten all vat lock screws.




2. Press  Position Build Plate > button.




PRINTING WITH T-1000

POSITIONING THE BUILD PLATE


3. Press <Yes> button to confirm.



The printer will position the build plate. Wait until all movement has stopped. (Fig. 4)



4. Tighten all vat lock screws.




PRINTING WITH T-1000

FILLING THE VAT

- ☰ Shake the resin bottle before each use.
- ⚠ Never overfill the vat past max line to avoid overflow and spill of resin inside the printer.

1. Pour resin into the vat before starting to print.



PRINTING

- ☰ The projector is set to a default XY resolution of 175 microns. If you will print a file with a different XY resolution, change the XY resolution setting of the projector and adjust the focus of the projector. The XY resolution of the projector should always match the XY resolution of the file.
- ☰ See “Adjusting the XY resolution of the projector” on page 37.
- ☰ See “Focusing the projector” on page 41.

1. Press < **G3D** / *it* > button to print.

SAFETY PRECAUTIONS


- ⚠ Do not stare at the UV light for prolonged period of time, it is equivalent to staring at the sun which can cause sunburn on your eyeball.
- ☰ The door window is UV protected. It should be closed during normal operations.

PRINTING WITH T-1000

PAUSE PRINTING

 Pausing is not advised.

1. Press  Pause> button.




You can add more resin during printing.

ABORT PRINTING

1. Press  Abort> button.

If you abort during printing, the build plate will move up and go back to its home position. Page will redirect to index page after 30 seconds.




ADJUSTING THE PROJECTOR

ADJUSTING THE XY RESOLUTION OF PROJECTOR


To effectively print a file, the XY resolution setting of the projector should have the same XY resolution indicated in the info box of G3D Web UI, if not issue will arise.

! Do not open the rear panel while the power is on. Before you remove the rear panel make sure to touch any metal frame of the printer to avoid electrostatic discharge damage.

1. Press <⏻> power button and hold it down for 5 seconds then release the power button. Wait until the light goes off.




2. Turn off main switch.




ADJUSTING THE PROJECTOR

ADJUSTING THE XY RESOLUTION OF PROJECTOR


3. Unplug the power cable.




4. Remove screws.



5. Lift the panel to open.



5.1




5.2


ADJUSTING THE PROJECTOR

ADJUSTING THE XY RESOLUTION OF PROJECTOR


6. Slightly untighten the projector adjuster knob to allow free movement.



7. Set the required XY resolution of the file.




8. Put the projector adjuster knob into the slot for lock position.




ADJUSTING THE PROJECTOR

ADJUSTING THE XY RESOLUTION OF PROJECTOR


9. Tighten the projector adjuster knob, just enough to secure from slipping.



10. Insert hook panel to close.



11. Return screws.




ADJUSTING THE PROJECTOR

FOCUSING THE PROJECTOR


It is essential to focus the projector properly after you have adjusted the XY resolution setting of the projector. Make sure to calibrate the vat and raise the build plate before you adjust the focus of the projector.

-  See “Calibrating the vat” on page 30.
-  See “Raising the build plate” on page 47.
-  Be alert of moving mechanism.

1. Remove the build plate lock screw.



2. Remove the build plate.




ADJUSTING THE PROJECTOR

FOCUSING THE PROJECTOR


 In preparation of focusing the projector, you need to open the front panel projector.

 Discharge static electricity.


3. Remove screws.



4. Lift to open the front panel projector.



4.1



4.2


5. Load a “G3D-TESTFILE-FOCUS” file with the same XY resolution setting as the printer.

XY RESOLUTION	CALIBRATION FOCUS TEST FILES
100 μm	G3D-TESTFILE-FOCUS-XY100.g3d
125 μm	G3D-TESTFILE-FOCUS-XY125.g3d
150 μm	G3D-TESTFILE-FOCUS-XY150.g3d
175 μm	G3D-TESTFILE-FOCUS-XY175.g3d



ADJUSTING THE PROJECTOR

FOCUSING THE PROJECTOR


6. Press <  Pre-Print File > button.



7. Place a white paper with a square outline on top of the vat, dimension should be 50mm x 50mm.



CALIBRATION SQUARE
FOR FOCUS TEST
50mm x 50mm



ADJUSTING THE PROJECTOR


FOCUSING THE PROJECTOR

8. Configure the following settings.

 Initial Layer Cure Time
20  
 No. of Initial Layer
1  
 Layers Cure Time
15  

 Wear safety glasses for uv light protection for prolong exposure.

9. Press < **G3D*it*** > button.



10. Ensure that the projected uv light of “G3D-TESTFILE-FOCUS” has identical dimension with the calibration square. The projected UV light should be sharp. If the uv light is blurred, adjust the focus ring of the projector.




ADJUSTING THE PROJECTOR


FOCUSING THE PROJECTOR

! Make sure not to drop the focus lock knob in the printer.


11. Slightly loosen the focus lock knob. Rotate the knob counter clockwise to a 360 degree only. Do not remove the focus lock knob from the projector.



12. Slowly dial the focus ring until the projected uv light of TestFocus appears sharp.




13. After focus is perfect, lock the focus lock knob.




ADJUSTING THE PROJECTOR

FOCUSING THE PROJECTOR


14. Press <Abort> button.



15. Insert and attach the front panel projector to the printer.



16. Return screws.



17. Attach the build plate to the bracket.

 See "Setting the vat" on page 13.

CLEANING GUIDE


RAISING THE BUILD PLATE

 This procedure is optional. Normally, after printing or aborting, the build plate will move up and go back to its home position.

1. Press < > cogwheel icon.



2. Press <Raise Plate> button.




REMOVING THE BUILD PLATE

 Do not remove the vat before the build plate to ensure that the resin will not drip inside the printer.

 Wear protective gloves.

 Wear safety glasses or goggles for eye protection.


1. Remove the build plate locking screw.



CLEANING GUIDE

REMOVING THE BUILD PLATE


2. Remove the build plate from bracket.



CLEANING GUIDE

G3D PRINT WORKSTATION KIT

The cleanliness of your printer is as important as cleaning your prints. Proper care is essential for longer lasting printing. The print workstation kit will help you organize your cleaning materials and cleaning process of your printer and prints.



- | | | | | | |
|---|------------------------|---|----------|---|--------------|
| 1 | Print Workstation Tray | 4 | Strainer | 7 | *Build Plate |
| 2 | Alcohol Tub | 5 | Funnel | 8 | *Clippers |
| 3 | Water Tub | 6 | *Bottle | 9 | *Scraper |


*Not included in the G3D print workstation kit.

*G3D Print Workstation Kit is optional, you can purchase separately.


CLEANING GUIDE

REMOVING THE PRINT

1. Place the build plate with print on a flat ground. Use a scraper to remove the print from the build plate.




2. Use clippers to remove supports.



CLEANING THE PRINT


1. Wash the print with grease cutting detergent soap.




CLEANING GUIDE

CLEANING THE PRINT


2. Rinse the print with clean water.



3. Place the print inside the alcohol tub.




4. Soak the print for 2-3 minutes inside the alcohol tub.



CLEANING GUIDE

CLEANING THE PRINT


1. Let the print dry on top of the strainer.




CLEANING THE VAT

- Never use alcohol or acetone when cleaning the vat.
- Store the resin bottle in a cool, dry and well ventilated area away from direct sunlight.
- Never mix used resin to new resin. Save old bottles for used resin storage.
- Strainer not included in the print workstation kit.

1. Remove resin debris inside the vat.




2. Use a strainer to separate resin from any solid particles. Pour the left over resin to an empty bottle.




CLEANING GUIDE

CLEANING THE VAT

3. Wash and apply grease cutting detergent soap into the vat. Perform a quick leak test if you need to check the vat.



4. Rinse the vat with clean water.
5. Wipe the vat with a paper towel.



CLEANING THE PROJECTOR

1. Power down the printer.
2. Use a microfiber cloth if projector has dust.
3. Gently wipe the lens in a circular motion.


CLEANING THE T-1000 AFTER PRINTING

1. Power down the printer.
2. Wipe the surface with a damp cloth to remove splash or splatter of resin.


VAT HANDLING

Prolong lifespan of vat with proper care and cleaning between prints. For best print results, ensure that the vat is always clean and scratch free.


- Do not remove the FEP film on the vat. It is for the vat's protection, manufacturer's warranty will be void if it's damaged or removed.



- When setting the vat, spout should be located at the back right of the printer and resin level indicator should be in front.



- Never use alcohol or acetone when cleaning the vat.



- Replace the vat if there are any cracks or leaks.
- Clean the vat after printing.
- Do not leave the resin inside the vat when not in use or printing.
- Do not expose the vat to excessive heat or direct sunlight.

TROUBLESHOOTING

Q1. Why does the print always peel away from the build plate during printing?

Please try the following:

1. Make sure to calibrate the vat and position the build plate before printing.
2. Make sure to tighten the build plate lock screw, vat locking screws and calibration levers.
3. Check and improve the support structures of your 3d model. For more complexed designs, add supports.
4. Make sure to add base to your 3d model.
5. Adjust the cure time settings. Refer to the resin time settings of the manufacturer.

Q2. Why is the print deformed or distorted after printing?

1. Make sure that the vat is clean and scratch-free.
2. Make sure that the projector is dust-free.
3. Make sure that your file and the projector is set to the correct XY resolution.
4. Adjust the focus of the projector.
5. Calibrate the vat and position the build plate.
6. Make sure that after printing you do not leave the print on the build plate hanging for prolong period of time.

Q3. Why is the print misaligned after printing?

1. Make sure that the build plate is clean and without any evidence of residue.
2. Make sure to tighten the vat lock screws and calibration levers.

CONTACT

SUPPORT

Our website has extensive documentation and troubleshooting information about your T-1000 3D printer. It's a great resource when you want to try to solve issues quickly on your own.

g3d@g3dsys.com

If you need help resolving an issue with your T-1000 UV 3D printer, email our G3D Support Team. To help us understand your problem from the start, please include pictures or a video as attachments to your email.

g3d@g3dsys.com

SALES

To learn about other G3D products, including G3D resin, please email us or visit our website.

g3d@g3dsys.com

FEEDBACK

We would love to hear from you, tell us what's on your mind.

g3d@g3dsys.com

RESIN CURE MATRIX

STD CLEAR 101V5

XY PROJECTOR SET	Z LAYER THICKNESS (microns)	INITIAL LAYER CURE TIME (seconds)	NUMBER OF INITIAL LAYER	LAYERS CURE TIME (seconds)
175	(L) 120 - 97.5	60 - 70	3	8 - 12
	90 - 67.5	60 - 70	3	8 - 12
	60 - 37.5	60 - 70	3	7 - 10
	30 - 7.5 (H)	60 - 70	3	7 - 8
150	(L) 120 - 97.5	50 - 60	3	6 - 12
	90 - 67.5	50 - 60	3	6 - 12
	60 - 37.5	50 - 60	3	6 - 10
	30 - 7.5 (H)	50 - 60	3	6 - 8
125	(L) 120 - 97.5	40 - 50	3	5 - 9
	90 - 67.5	40 - 50	3	5 - 9
	60 - 37.5	40 - 50	3	5 - 8
	30 - 7.5 (H)	40 - 50	3	5 - 7
100	(L) 120 - 97.5	35 - 40	3	4 - 8
	90 - 67.5	35 - 40	3	4 - 8
	60 - 37.5	35 - 40	3	4 - 7
	30 - 7.5 (H)	35 - 40	3	4 - 7

■ Optimal Settings | (L) - Lowest Resolution | (H) - Highest Resolution

STD YELLOW-T 102V1

XY PROJECTOR SET	Z LAYER THICKNESS (microns)	INITIAL LAYER CURE TIME (seconds)	NUMBER OF INITIAL LAYER	LAYERS CURE TIME (seconds)
175	(L) 120 - 97.5	60 - 70	3	7 - 12
	90 - 67.5	60 - 70	3	7 - 12
	60 - 37.5	60 - 70	3	7 - 10
	30 - 7.5 (H)	60 - 70	3	7 - 10
150	(L) 120 - 97.5	55 - 65	3	7 - 10
	90 - 67.5	55 - 65	3	7 - 10
	60 - 37.5	55 - 65	3	7 - 8
	30 - 7.5 (H)	55 - 65	3	7 - 8
125	(L) 120 - 97.5	40 - 50	3	6 - 8
	90 - 67.5	40 - 50	3	6 - 8
	60 - 37.5	40 - 50	3	6 - 7
	30 - 7.5 (H)	40 - 50	3	6 - 7
100	(L) 120 - 97.5	35 - 40	3	3 - 7
	90 - 67.5	35 - 40	3	3 - 7
	60 - 37.5	35 - 40	3	3 - 6
	30 - 7.5 (H)	35 - 40	3	3 - 6

■ Optimal Settings | (L) - Lowest Resolution | (H) - Highest Resolution

RESIN CURE MATRIX

STD RED-T 103V1

XY PROJECTOR SET	Z LAYER THICKNESS (microns)	INITIAL LAYER CURE TIME (seconds)	NUMBER OF INITIAL LAYER	LAYERS CURE TIME (seconds)
175	(L) 120 - 97.5	60 - 70	3	7 - 12
	90 - 67.5	60 - 70	3	7 - 12
	60 - 37.5	60 - 70	3	7 - 10
	30 - 7.5 (H)	60 - 70	3	7 - 10
150	(L) 120 - 97.5	55 - 65	3	7 - 10
	90 - 67.5	55 - 65	3	7 - 10
	60 - 37.5	55 - 65	3	7 - 8
	30 - 7.5 (H)	55 - 65	3	7 - 8
125	(L) 120 - 97.5	40 - 50	3	6 - 8
	90 - 67.5	40 - 50	3	6 - 8
	60 - 37.5	40 - 50	3	6 - 7
	30 - 7.5 (H)	40 - 50	3	6 - 7
100	(L) 120 - 97.5	35 - 40	3	3 - 7
	90 - 67.5	35 - 40	3	3 - 7
	60 - 37.5	35 - 40	3	3 - 6
	30 - 7.5 (H)	35 - 40	3	3 - 6

■ Optimal Settings | (L) - Lowest Resolution | (H) - Highest Resolution

STD BLUE-T 104V1

XY PROJECTOR SET	Z LAYER THICKNESS (microns)	INITIAL LAYER CURE TIME (seconds)	NUMBER OF INITIAL LAYER	LAYERS CURE TIME (seconds)
175	(L) 120 - 97.5	60 - 70	3	7 - 12
	90 - 67.5	60 - 70	3	7 - 12
	60 - 37.5	60 - 70	3	7 - 10
	30 - 7.5 (H)	60 - 70	3	7 - 10
150	(L) 120 - 97.5	55 - 65	3	7 - 10
	90 - 67.5	55 - 65	3	7 - 10
	60 - 37.5	55 - 65	3	7 - 8
	30 - 7.5 (H)	55 - 65	3	7 - 8
125	(L) 120 - 97.5	40 - 50	3	6 - 8
	90 - 67.5	40 - 50	3	6 - 8
	60 - 37.5	40 - 50	3	6 - 7
	30 - 7.5 (H)	40 - 50	3	6 - 7
100	(L) 120 - 97.5	35 - 40	3	3 - 7
	90 - 67.5	35 - 40	3	3 - 7
	60 - 37.5	35 - 40	3	3 - 6
	30 - 7.5 (H)	35 - 40	3	3 - 6

■ Optimal Settings | (L) - Lowest Resolution | (H) - Highest Resolution

RESIN CURE MATRIX

STD GRAY-T 107V1

XY PROJECTOR SET	Z LAYER THICKNESS (microns)	INITIAL LAYER CURE TIME (seconds)	NUMBER OF INITIAL LAYER	LAYERS CURE TIME (seconds)
175	(L) 120 - 97.5	70 - 80	3	10 - 14
	90 - 67.5	70 - 80	3	10 - 14
	60 - 37.5	70 - 70	3	8 - 12
	30 - 7.5 (H)	70 - 70	3	8 - 12
150	(L) 120 - 97.5	60 - 70	3	9 - 12
	90 - 67.5	60 - 70	3	9 - 12
	60 - 37.5	55 - 65	3	8 - 10
	30 - 7.5 (H)	55 - 65	3	8 - 10
125	(L) 120 - 97.5	55 - 65	3	8 - 10
	90 - 67.5	55 - 65	3	8 - 10
	60 - 37.5	45 - 55	3	7 - 8
	30 - 7.5 (H)	45 - 55	3	7 - 8
100	(L) 120 - 97.5	45 - 55	3	4 - 7
	90 - 67.5	45 - 55	3	4 - 7
	60 - 37.5	35 - 40	3	4 - 6
	30 - 7.5 (H)	35 - 40	3	4 - 6

■ Optimal Settings | (L) - Lowest Resolution | (H) - Highest Resolution

